C SERVICING AND TROUBLESHOOTING - REGIONAL 2017	Contestant Number:	
AGE 1 OF 9		
AGE 1 OF 7	Time:	

Time:	
Rank:	

PC SERVICING AND TROUBLESHOOTING (305)

REGIONAL – 2017

TOTAL POINTS	(500 points)
	(300 points)

Failure to adhere to any of the following rules will result in disqualification:

- 1. Contestant must hand in this test booklet and all printouts. Failure to do so will result in disqualification.
- 2. No equipment, supplies, or materials other than those specified for this event are allowed in the testing area. No previous BPA tests and/or sample tests or facsimile (handwritten, photocopied, or keyed) are allowed in the testing area.
- 3. Electronic devices will be monitored according to ACT standards.

No more than sixty (60) minutes testing time

Property of Business Professionals of America.

May be reproduced only for use in the Business Professionals of America

Workplace Skills Assessment Program competition.

PC SERVICING AND TROUBLESHOOTING - REGIONAL 2017 PAGE 2 OF 9

Identify the letter of the choice that best completes the statement or answers the question.

- 1. Which of the following configurations would be set after installing a new modem card?
 - a. Proxy server settings
 - b. Workgroup name
 - c. COM port number
 - d. Expansion port
- 2. Which of the following devices would need to be configured to block specific ports and protocols from entering the network?
 - a. Bridge
 - b. Firewall
 - c. Port replicator
 - d. Gateway
- 3. Which of the following is the *appropriate* interface to connect an optical mouse and keyboard to a computer?
 - a. IEEE 1394
 - b. USB
 - c. Serial
 - d. eSATA
- 4. Which of the following memory features allows for the protection against random inconsistencies in the transfer of the data?
 - a. Low latency
 - b. Dual channel
 - c. ECC
 - d. Single channel
- 5. Which of the following memory types is *most* commonly found in Pentium 4 class and newer desktop PCs?
 - a. SIMM
 - b. RAMBUS
 - c. SODIMM
 - d. DIMM
- 6. A workstation would *most* likely be connected to an office network using which of the following cable types?
 - a. eSATA
 - b. Bluetooth
 - c. SCSI
 - d. Ethernet

PC SERVICING AND TROUBLESHOOTING - REGIONAL 2017 PAGE 3 OF 9

- 7. Which of the following terms *best* describes the software or hardware used to manage virtual machines?
 - a. Hypervisor
 - b. Cloud Server Manager
 - c. Supervisor
 - d. Virtual Disk Manager
- 8. Which of the following safety devices would be employed to prevent static discharge between a computer and a technician?
 - a. Non-Magnetic screwdriver
 - b. Voltmeter
 - c. Electrical tape
 - d. ESD mat
- 9. To configure two drives for *maximum* performance, which of the following RAID types should be used?
 - a. RAID 0
 - b. RAID 1
 - c. RAID 5
 - d. RAID 10
- 10. A technician is tasked with selecting components to build a computer that will be used for computer-aided drafting and computer aided modeling. Which of the following components is the *best* choice?
 - a. Triple channel memory
 - b. Hi-end MIDI sound card
 - c. TV tuner
 - d. Dedicated graphics card
- 11. Which of the following wireless protocols is limited to operating in the 5 GHz range ONLY?
 - a. 802.11a
 - b. 802.11b
 - c. 802.11g
 - d. 802.11n
- 12. Which of the following printing technologies uses piezoelectric pressure pads to produce small bubbles that are moved to the paper?
 - a. Impact
 - b. Thermal
 - c. Laser
 - d. Inkjet

PC SERVICING AND TROUBLESHOOTING - REGIONAL 2017 PAGE 4 OF 9

- 13. When installing a printer in Windows, which of the following is the purpose of the Additional Drivers button on the Sharing tab in the printer's properties?
 - a. To add additional drivers to emulate a different printer
 - b. To add additional drivers for other printers on the computer
 - c. To add additional drivers for other operating systems
 - d. To add additional drivers for different printing mode
- 14. Which of the following Control Panel utilities will allow a technician to change a firewall setting?
 - a. System and security
 - b. Administrator tools
 - c. Accessibility options
 - d. Regional and language options
- 15. Which of the following will help protect against brownouts?
 - a. Power supply
 - b. Anti-static strap
 - c. Surge suppressor
 - d. Battery backup
- 16. ECC memory with parity is primarily used in which of the following computers?
 - a. Tablet
 - b. Desktop
 - c. Server
 - d. Laptop
- 17. Which of the following protocols would an email client use?
 - a. HTTP
 - b. SNMP
 - c. SMTP
 - d. SFTP
- 18. Which of the following standards would be used on a wireless router to support speeds up to 150 Mbps?
 - a. 802.11a
 - b. 802.11b
 - c. 802.11g
 - d. 802.11n
- 19. Which of the following should a technician check *first* before upgrading the RAM in a laptop?
 - a. The speed of the FSB
 - b. The motherboard specifications
 - c. The BIOS manufacturer
 - d. The operating system version

PC SERVICING AND TROUBLESHOOTING - REGIONAL 2017 PAGE 5 OF 9

- 20. A printer is *not* pulling paper out of the paper tray. Which of the following is the *most* possible cause of the problem?
 - a. Pickup rollers
 - b. DC Power problem
 - c. Faulty Drum cleaning blade
 - d. Room temperature in room too cold
- 21. A technician is *not* able to boot to Windows OS. A "Non bootable device found" message appears on the screen when the computer restarts. Which of the following is the *most* possible cause of the error message?
 - a. MBR is corrupt on the HDD.
 - b. HDD is set to Cable Select.
 - c. The operating system is corrupt.
 - d. A bootable HDD is not recognized in the BIOS.
- 22. Which of the following keys, when pressed while clicking "restart," will display boot options on a Windows 10 PC?
 - a. Shift
 - b. f8
 - c. esc
 - d. f2
- 23. Which of the following is the *correct* pin out for T568B?
 - a. Orange/white, orange, green/white, blue, blue/white, green, brown/white, brown
 - b. Blue, blue/white, orange/white, orange, brown/white, brown, green/white, green
 - c. Green/white, green, orange/white, blue, blue/white, orange, brown/white, brown
 - d. Orange/white, orange, brown/white, brown, green/white, green, blue, blue/white
- 24. Which of the following lists the *correct* non-overlapping channels in 2.4 GHz?
 - a. 1, 6, 11
 - b. 2, 4, 6, 8, 10
 - c. 3, 6, 9
 - d. 5, 11
- 25. A home user working outside an office reports that their laptop is no longer connecting to the Internet. Which of the following would a technician recommend to check *first*?
 - a. Windows Firewall settings
 - b. DHCP settings
 - c. Disable HomeGroup
 - d. Wireless on/off switch
- 26. A technician installed a new docking station for a user, and they have lost the ability to connect to the network. Which of the following is the *most* likely reason?
 - a. DHCP is disabled
 - b. The network is down
 - c. Device drivers are not loaded
 - d. The product is not compatible

PC SERVICING AND TROUBLESHOOTING - REGIONAL 2017 PAGE 6 OF 9

- 27. Which of the following expansion ports is typically brown in color?
 - a. PCI
 - b. PCI-X
 - c. PCIe
 - d. AGP
- 28. Which of the following connector types uses a single RCA style connector?
 - a. DVI
 - b. VGA
 - c. RGB
 - d. Composite video
- 29. Which of the following Windows 8.1 versions comes with AppLocker built in?
 - a. Enterprise
 - b. Home
 - c. Professional
 - d. RT
- 30. Which of the following laptop displays would provide the best viewing angle?
 - a. Active matrix
 - b. TFT LCD
 - c. IPS
 - d. Plasma
- 31. When setting up for a projector presentation, which of the following laptop function keys usually needs to be toggled?
 - a. Contrast
 - b. Brightness
 - c. Display
 - d. Bluetooth
- 32. A user, Ann, states that her laser printer has a smudge that repeats itself every couple inches down the center of each page. Which of the following components *most* likely needs replacing?
 - a. Rollers
 - b. Fuser
 - c. Toner drum
 - d. Pickup assembly
- 33. A laptop's wireless card shows up in the Device Manager, but the signal strength is always one bar. This is caused by which of the following?
 - a. The signal is disabled in the wireless utility
 - b. Disconnected or broken antenna
 - c. Disconnected or broken inverter
 - d. The wireless switch is turned off

PC SERVICING AND TROUBLESHOOTING - REGIONAL 2017 PAGE 7 OF 9

a.	of the following cables is prone to electromagnetic interference? STP
b.	PVC
c.	Plenum
d.	UTP
	is a designation for which of the following cable types?
	Plenum
	Fiber optic
	Twisted pair
d.	Coaxial
36. Which	of the following ports is used by default for DNS traffic?
	25
	53
	143
d.	3389
	nician wants to know if a PC has an embedded wireless card. Which of the following hould be used?
a.	Device Manager
	Component Services
	Services
d.	System Configuration
38. Which	of the following ports is used for SMTP traffic by default?
a.	110
	25
	143
	443
	of the following is the <i>first</i> thing a technician should do before putting their hand
	a computer case?
	Acquire the appropriate tools that are going to be used.
	Touch the case to discharge static.
c.	Remove loose jewelry.
d.	Refer to manufacturer documentation.
40. Which	of the following socket types is for an Intel CPU?
a.	F
b.	940
c.	AM3
d.	1156

PC SERVICING AND TROUBLESHOOTING - REGIONAL 2017 PAGE 8 OF 9

- 41. Which of the following cable types is *most* often found in new phone wiring?
 - a. RG-6
 - b. CAT3
 - c. Cat5E
 - d. Multi-mode
- 42. A technician notices multiple disk errors in the Event Viewer. Which of the following tools would *best* diagnose this issue?
 - a. CHKDSK
 - b. FDISK
 - c. BOOTREC
 - d. DISKPART
- 43. The term SFF refers to which of the following?
 - a. CPU speed
 - b. Memory size
 - c. Motherboard size
 - d. HDD size
- 44. A threaded coaxial connector used to connect to a TV tuner is *most* often referred to as which of the following?
 - a. F-connector
 - b. RJ-11 connector
 - c. IEEE 1394 connector
 - d. RJ-45 connector
- 45. The MAXIMUM transfer rate of modern eSATA is which of the following?
 - a. 1.54 Mbps.
 - b. 2.0 Gbps.
 - c. 6.0 Gbps.
 - d. 480 Mbps.
- 46. A technician installs a new high-end gaming video card into a computer but is not seeing any video. Which of the following power connectors did the technician *most* likely forget to install?
 - a. 4/8-pin 12v
 - b. 6 or 8-pin PCIe
 - c. 20-pin main
 - d. 24-pin main
- 47. Which of the following should a technician do *first* after receiving a call from a customer asking for assistance?
 - a. Confirm the user and the associated issue.
 - b. Confirm the hardware make, model, and serial number.
 - c. Escalate the call to a supervisor.
 - d. Assign the appropriate status for the problem.

PC SERVICING AND TROUBLESHOOTING - REGIONAL 2017 PAGE 9 OF 9

- 48. Which of the following laptop hardware components requires a re-soldering process in order to replace properly?
 - a. Mini PCIe wireless card
 - b. Heat sink
 - c. DC jack
 - d. Li-Ion battery
- 49. Which of the following BIOS boot methods allows a system to boot from a remote server?
 - a. PXE
 - b. DVD
 - c. USB
 - d. SATA
- 50. Ann gets motion sickness symptoms when using her new computer monitor. Which of the following can a technician adjust to help Ann?
 - a. Privacy filter
 - b. Refresh rate
 - c. Use a digital signal
 - d. Brightness